Index of 1975 articles

TITLES OF ARTICLES

All About Rectification ..... Oct. 34
Answers About MATV Specs ..... Jan. 20
Build A Transistor-Test Adapter ..... Mar. 21
Case Of The Howling TV ..... Mar. 24
Cassette Or Machine At Fault? ..... Feb. 19
Clues From The Big Scope ..... May 28
Electronic Merry-Go-Round (puzzle) ..... Sep. 43
Forest Belt's 8-Track Workshop, Part 1 ..... Oct. 23
Forest Belt's 8-Track Workshop, Part 2 ..... Nov. 36
Forest Belt's 8-Track Workshop, Part 3 ..... Dec. 28
FM-Stereo Circuits ..... Jun. 26
Goodbye, Color Controls! ..... Mar. 15
Goodbye, TV Ghosts! ..... Nov. 14
Heat It! Cool It! ..... Aug. 13
Hi, Resistance! (puzzle) ..... Nov. 26
How To Exorcise A Cow ..... May 20
Index of 1974 Articles ..... Jan. 35
Interlaced Scanning . . . Fact And Myth ..... Feb. 34
Installing CB Radio In Trucks ..... Dec. 12
Just-Across-Word (puzzle) ..... May 27
Lady TV "Serviceman" ..... Mar. 20
Medical Electronics Notebook, Part 1 ..... Sep. 28
More Favorite Repairs ..... Aug. 26
My Favorite Repairs ..... Jan. 12
My Tuner Tips ..... Apr. 34
NESDA & NATESA Conventions ..... Oct. 3
Often-Used Tubes ..... Dec. 17
Op-Amps . . . Solid-State Versatility ..... Jun. 17
Our Current Puzzler (puzzle) ..... Jan. 38
Practical Bookkeeping ..... Jul. 18
Planning Small MATV ..... May 14
Pretty Technicians ..... Jul. 13
Pricing Versus Consumerism ..... Apr. 22
Reader's Chuckles ..... Jan. 18
Scan Rectification ..... Sep. 34
Selecting Ladders ..... Apr. 26
Selective Radio Calling, Part 1 ..... Jul. 14
Selective Radio Calling, Part 2 ..... Aug. 18
Servicer's Day In France ..... Mar. 12
Servicing Audio, Part 1 ..... Sep. 14
Servicing Audio, Part 2 ..... Oct. 30
Servicing Audio, Part 3 ..... Nov. 28
Servicing Audio, Part 4 ..... Dec. 22
Servicing Direct-Coupled Audio ..... May 21
Servicing Modular Color, Part 1 (Zenith) ..... Feb. 11
Servicing Modular Color, Part 2 (Zenith) ..... Mar. 25
Servicing Modular Color, Part 3 (Zenith) ..... Apr. 37
Servicing Modular Color, Part 4 (Zenith) ..... May 34
Servicing Modular Color, Part 5 (Zenith) ..... Jun. 32
Servicing Modular Color, Part 6 (Quasar) ..... Jul. 25
Servicing Modular Color, Part 7 (Quasar) ..... Aug. 31
Servicing RCA XL-100, Part 1 ..... Nov. 43
Servicing RCA XL-100, Part 2 ..... Dec. 33
Spanish Batteries ..... Aug. 41
Starting A CB Business ..... Oct. 17
Station Wagon Or Van? ..... Sep. 22
Tax Court . . . Help For Small Claims ..... Jun. 14
Through Sky To $1,700,000 ..... Jun. 10
Time Those Short Circuits ..... Nov. 20
Time To Go Ohm (puzzle) ..... Oct. 16
Troubleshooting Philco Hybrids ..... Apr. 12
Tuner Or Chassis? ..... Dec. 18
Video Tape Recorders, Part 2 ..... Jul. 30
Who's Cheating Whom? ..... Aug. 12
Wiring CB Coax Connectors ..... Sep. 30
Workshop On Cassette Recorders, Part 3 ..... Jan. 28
Workshop On Cassette Recorders, Part 4 ..... Feb. 28
You Know Watt? (puzzle) ..... Aug. 35

ANTENNA, MATV, CATV

Answers About MATV Specs ..... Jan. 20
Planning Small MATV ..... May 14
Selecting Ladders ..... Apr. 26

AUDIO

Cassette Or Machine At Fault? ..... Feb. 19
Forest Belt's 8-Track Workshop, Part 1 ..... Oct. 23
Forest Belt's 8-Track Workshop, Part 2 ..... Nov. 36
Forest Belt's 8-Track Workshop, Part 3 ..... Dec. 28
FM-Stereo Circuits ..... Jun. 26
Op-Amps . . . Solid-State Versatility ..... Jun. 17
Servicing Audio, Part 1 ..... Sep. 14
Servicing Audio, Part 2 ..... Oct. 30
Servicing Audio, Part 3 ..... Nov. 28
Servicing Audio, Part 4 ..... Dec. 22
Servicing Direct-Coupled Audio ..... May 21
Workshop On Cassette Recorders, Part 3 ..... Jan. 28
Workshop On Cassette Recorders, Part 4 ..... Feb. 28

BUSINESS

Practical Bookkeeping ..... Jul. 18
Pricing Versus Consumerism ..... Apr. 22
Starting A CB Business ..... Oct. 17
Station Wagon Or Van? ..... Sep. 22
Tax Court . . . Help For Small Claims ..... Jun. 14
Through Sky To $1,700,000 ..... Jun. 10
Who's Cheating Whom? ..... Aug. 12

COLOR TV

Case Of The Howling TV ..... Mar. 24
Clues From The Big Scope ..... May 28
Goodbye, Color Controls! ..... Mar. 15
Goodbye, TV Ghosts! ..... Nov. 14
Heat It! Cool It! ..... Aug. 13
Interlaced Scanning . . . Fact And Myth ..... Feb. 34
My Favorite TV Repairs ..... Jan. 12
More Favorite Repairs ..... Aug. 26
My Tuner Tips ..... Apr. 34
Scan Rectification ..... Sep. 34
Servicing Modular Color, Part 1 (Zenith) ..... Feb. 11
Servicing Modular Color, Part 2 (Zenith) ..... Mar. 25
Servicing Modular Color, Part 3 (Zenith) ..... Apr. 37
Servicing Modular Color, Part 4 (Zenith) ..... May 34
Servicing Modular Color, Part 5 (Zenith) ..... Jun. 32
Servicing Modular Color, Part 6 (Quasar) ..... Jul. 25
Servicing Modular Color, Part 7 (Quasar) ..... Aug. 31
Servicing RCA XL-100, Part 1 ..... Nov. 43
Servicing RCA XL-100, Part 2 ..... Dec. 33
Time Those Short Circuits ..... Nov. 20
Troubleshooting Philco Hybrids ..... Apr. 12
Tuner Or Chassis? ..... Dec. 18
Video Tape Recorders ..... Jul. 30

HORIZONTAL AND HIGH VOLTAGE

Scan Rectification ..... Sep. 34
Servicing Modular Color, Part 2 (Zenith) ..... Mar. 25
Time Those Short Circuits ..... Nov. 20

MISCELLANEOUS

All About Rectification ..... Oct. 34
Case Of The Howling TV ..... Mar. 24
Heat It! Cool It! ..... Aug. 13
How To Exorcise A Cow ..... May 20
Index Of 1974 Articles ..... Jan. 35
Interlaced Scanning . . . Fact And Myth ..... Feb. 34
Lady TV "Serviceman" ..... Mar. 20
Medical Electronics Notebook, Part 1 ..... Sep. 28
NESDA & NATESA Conventions ..... Oct. 3
Often-Used Tubes ..... Dec. 17
Pretty Technicians ..... Jul. 13
Pricing Versus Consumerism ..... Apr. 22
Reader's Chuckles ..... Jan. 18
Selecting Ladders ..... Apr. 26
Servicer's Day In France ..... Mar. 12
Spanish Batteries ..... Aug. 41
Video Tape Recorders, Part 2 ..... Jul. 30

PUZZLES

Electronic Merry-Go-Round ..... Sep. 43
Hi, Resistance! ..... Nov. 26
Just-Across-Word Puzzle ..... May 27
Our Current Puzzler ..... Jan. 38
Time To Go Ohm ..... Oct. 16
You Know Watt? ..... Aug. 35

RADIO COMMUNICATIONS

Installing CB Radio In Trucks ..... Dec. 12
Selective Radio Calling, Part 1 ..... Jul. 14
Selective Radio Calling, Part 2 ..... Aug. 18
Starting A CB Business ..... Oct. 17
Wiring CB Coax Connectors ..... Sep. 30

REPORTS FROM THE TEST LAB

Health Model SO-4510 scope ..... May 40
Hewlett-Packard Model 1220A scope ..... Feb. 23
Hickok Models 220 and 215 transistor testers ..... Mar. 35
Hickok Model 440 SS curve tracer ..... Sep. 44
Jerrold Model TRC-12 remote control ..... Jan. 25
Lectrotech TO-60 scope, BG-10 color-bar generator, and SCA-300 sweep substitutor ..... Jul. 40
RCA Model WR-515A color-bar generator ..... Jun. 40
Tektronix TM-500 series of modules ..... Dec. 42

SOLID STATE

Build a Transistor-Test Adapter ..... Mar. 21
FM-Stereo Circuits ..... Jun. 26
Heat It! Cool It! ..... Aug. 13
Op-Amps . . . Solid-State Versatility ..... Jun. 17
Servicing Direct-Coupled Audio ..... May 21
Troubleshooting Philco Hybrids ..... Apr. 12

VERTICAL SWEEP

Servicing Modular Color, Part 3 (Zenith) ..... Apr. 37
Servicing RCA XL-100 ..... Dec. 33

SYMCURE

GENERAL ELECTRIC

C-2 insufficient height ..... Dec. 8
C-2 stretched at top ..... Dec. 8
C-2 no height ..... Dec. 8
C-2 fast roll ..... Dec. 8
C-2 stretched at top ..... Dec. 8
C-2 insufficient height ..... Dec. 8

GTE-SYLVANIA

D12 low HV, locking drifts ..... Nov. 8
D16 narrow at right ..... Nov. 8
D12 AGC overload ..... Jun. 8
D12 noise in pix, also radiates ..... Jun. 8
D16 weak or no chroma ..... Jun. 8
D16 oscillations radiate to other sets ..... Jun. 8
D17 no color ..... Feb. 8
D17 insufficient brightness ..... Feb. 8
D17 vertical locking intermittent ..... Feb. 8
D19 no HV, or narrow picture ..... Nov. 8
D19 vertical hold at one end ..... Nov. 8
D19 no height ..... Nov. 8
E03 heavy hum bars ..... Feb. 8
E03 no height ..... Feb. 8
E03 intermittent height ..... Feb. 8
E06 smeared, low-contrast picture ..... Nov. 8
E06 no sound or pix ..... Jun. 8
E06 white horiz. line at top ..... Jun. 8

MAGNAVOX

T989 broad vertical bars at left ..... Oct. 8
T989 focus control at end ..... Oct. 8
T989 excessive contrast with Videomatic ..... Oct. 8
T989 dark half-circle at top ..... Oct. 8
T989 squeal from horiz. output ..... Oct. 8
T989 Q4, RF transistor, fails ..... Oct. 8

PHILCO-FORD

2CY80 brightness too high or too low ..... Apr. 8
2CY80 color has only weak green ..... Apr. 8
2CY80 pix bends with brightness ..... Apr. 8
2CY80 no high voltage ..... Apr. 8
2CY80 vertical roll ..... May 8
2CY80 no pix, no sound ..... May 8
3CY90 snow, or blank raster ..... Apr. 8
3CY90 no raster, or low HV ..... Apr. 8

RCA

CTC46 video smear ..... Mar. 8
CTC46 horizontal locking critical ..... Sep. 8
CTC48 decreased height ..... Sep. 8
CTC48 low HV ..... Sep. 8
CTC48 no control of brightness ..... Jul. 8
CTC48 vertical collapse when bright ..... Jul. 8
CTC51, CTC52, CTC53 poor converg at bot. ..... Jul. 8
CTC53 no green in color ..... Jul. 8
CTC53 no sound, or intermittent ..... May 8
CTC58 poor gray tracking, green smear ..... Jul. 8
CTC58 video smear ..... Jul. 8
CTC58 herringbone with AFT ..... Sep. 8
CTC58 black vert line at left ..... Sep. 8
CTC58 intermittent blooming or arcing ..... Sep. 8
CTC58 no volume or distorted sound ..... Mar. 8
CTC58 low brightness ..... Mar. 8
CTC62 slow warmup ..... Mar. 8
CTC63 insufficient height ..... Mar. 8
CTC68 inoperative hold-down ..... Mar. 8

SYLVANIA (SEE GTE-SYLVANIA)

ZENITH

17/19EC45 no vertical ..... Jan. 8
17/19EC45 no raster ..... Jan. 8
17/19EC45 poor gray scale tracking ..... Jan. 8
17/19EC45 120-Hz hum in pix ..... Jan. 8
17/19EC45 excessive HV ..... Jan. 8
17/19EC45 bending at high brightness ..... Jan. 8
17/19EC45 white vertical line ..... Aug. 10
20Y1C46 insufficient height ..... May 8
23DC14 excessive brightness ..... Aug. 10
25CC25 insufficient height ..... Aug. 10
25CC25 no height ..... Aug. 10
25DC56 loud hum, white horiz bar ..... Aug. 10
25DC56 flashing and 120-Hz hum in pix ..... Aug. 10

TROUBLESHOOTING TIPS

ADMIRAL

H1-1A (b-w) no high voltage ..... Nov. 9

GENERAL TOPICS

Slipping idler wheels ..... Nov. 9
Testing gain of stereo channels ..... Feb. 10

GENERAL ELECTRIC

H-1 no color ..... Mar. 10
H-4 intermittent HV ..... Mar. 11
KE-II excessive brightness ..... Jan. 10

GTE-SYLVANIA

D18 green at left edge ..... Jan. 10

HITACHI

CWA200 horiz transistor failures ..... Sep. 12

MGA

GS-170 no DC power ..... Jun. 44

MOTOROLA

TS-938 "whale" in picture ..... Jul. 10

PACKARD BELL

98C32 intermittent sound ..... Sep. 12

PANASONIC

AN-409TA (b-w) won't turn off ..... Mar. 10
RQ309 (tape) no sound from head ..... Mar. 10

PHILCO-FORD

3CR40 no blue in raster ..... Feb. 10
19FT60B intermittent convergence ..... Nov. 10
19FT60B intermittent color ..... Mar. 11
20QT90 HV rectifier fails ..... Oct. 13

RCA

CTC24 no reason for hot resistor ..... May 13
CTC25 intermittent height ..... Mar. 11
CTC38 excessive brightness ..... Aug. 7
CTC38 video flutter ..... May 12
CTC42XP intermittent height ..... Dec. 10
rectangular models with trapezoidal raster ..... Jan. 10
CTC49XA no HV, burned resistor ..... Mar. 10
CTC51 no picture, no sound ..... Apr. 10
CTC55 dim and erratic brightness ..... Aug. 7
CTC55 shrinking height ..... Dec. 10
KCS155 (b-w) weak vertical sync ..... Jan. 10
KCS169B (b-w) raster, but no pix ..... Oct. 13

SEARS SILVERTONE

529.726600 color at left edge ..... May 12
529.72940 excessive HV ..... Oct. 14
562.10220 intermittent color lock ..... Mar. 10

SONY

SCC-08 dark picture ..... Aug. 8

ZENITH

12A10C15 vertical problems ..... Jun. 44
16Z8C50 blackout and arcing ..... May 12
18CC29 excessive red ..... Dec. 10
19EB12 (b-w) transistor failures ..... Nov. 9
19EC45 low brightness ..... Nov. 10
19EC45 pulsating hum ..... Jul. 10
23XC36 bounce at bottom of pix ..... Jan. 10

□